Health o meter®
Professional
Pelstar, LLC • 9500 West 55th St. • McCook, IL 60525-7110 • USA • Phone: 800-815-6615 • Fax: 800-654-7330

349KLX AUTO-OFF Function

To extend battery life, the scale is programmed to automatically shut off after 2 minutes of inactivity. This function is ENABLED by default. To DISABLE this function, follow the procedure below.

NOTE: Ensure that the load cell cable is plugged into the display head, and there is nothing on the scale platform.

DISABLE AUTO-OFF

1. While the scale is powered off, press and hold the **lb/kg** button.
2. While holding the **lb/kg** button, press the **ON** button to turn the scale on.
3. "**349**" will briefly appear on the display, followed by "**A-OF**", and then "**0.0**" appears.
4. Release the **lb/kg** and **ON** button.
5. The AUTO-OFF function is now DISABLED, and the scale will remain on until it is manually shut off.

ENABLE AUTO-OFF

1. While the scale is powered off, press and hold the **lb/kg** button.
2. While holding the **lb/kg** button, press the **ON** button to turn the scale on.
3. "**349**" will briefly appear on the display, followed by "**0.0**".
4. Release the **lb/kg** and **ON** button.
5. The AUTO-OFF function is now ENABLED, and the scale will automatically shut off after 2 minutes of inactivity.